

Part Number: 1028

SAFETY DATA SHEET (SDS)

Revision Date: 02/21/2018 Version 1.0

1. PRODUCT AND COMPANY IDENTIFICATION

1.1	Product Name: Part Number: CAS-No.: SDS Number:	Calibration Buffer, pH 10.00 1028 Not applicable 5010	
1.2	Recommended Use:	Laboratory Chemicals	
1.3	Company:	Newcomer Supply 2505 Parview Road Middleton, WI 53562 USA	24 HOUR EMERGENCY CONTACT CALL CHEMTREC: 1-800-424-9300
	Telephone:	1-800-383-7799	Contact CHEMTREC only in the event of
	Fax:	1-608-831-0866	an emergency involving a chemical spill,
	Website:	www.newcomersupply.com	leak, fire, exposure or other accident.
	Email:	info@newcomersupply.com	

2. HAZARD(S) IDENTIFICATION

2.1 Classification of the substance or mixture GHS Classification, (in accordance with 29 CFR1910.1200) Reproductive toxicity, Category 2

2.2 GHS Label elements Signal Word WARNING

Pictogram



Hazard Statement(s):

 \cdot Suspected of damaging fertility or the unborn child

Precautionary Statement(s):

Prevention:

- \cdot Obtain special instructions before use.
- · Do not handle until all safety precautions have been read and understood.
- · Wear protective gloves/protective clothing/eye protection/face protection.

Response:

- IF exposed or concerned: Get medical advice/attention. **Storage:**
- · Store locked up.
- Disposal:
- Dispose of contents/ container to an approved waste disposal plant.
- 2.3 Description of any hazards not otherwise classified None
- 2.4 >1% of mixture with unknown acute toxicity None

3. COMPOSITION/INFORMATION ON INGREDIENTS

3.2 Mixture

Hazardous Components

Compone	nt	Concentration	
Name	Potassium Chloride		
CAS-No.	7447-40-7	1%	
Name	Boric Acid		
CAS-No.	10043-35-3	1%	
Name	Sodium Hydroxide		
CAS-No.	1310-73-2	1%	

4. FIRST-AID MEASURES



SAFETY DATA SHEET (SDS)

Revision Date: 02/21/2018

Version 1.0

Part Number: 1028

4.1 Description of necessary measures

Inhalation (breathing)

IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. IF exposed or concerned: Get medical advice/attention.

Skin Contact

IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. IF exposed or concerned: Get medical advice/attention.

Eye Contact

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses if present and easy to do – continue rinsing. If eye irritation persists get medical advice/attention.

Ingestion (swallowed)

IF SWALLOWED: Call a POISON CENTER or doctor/physician if you feel unwell. Rinse mouth.

- **4.2** Most important symptoms and or effects, acute and delayed The most important symptoms/effects are presented in Section 2 and or Section 11.
- **4.3 Indication of any immediate medical attention and special treatment needed** No data available

5. FIRE-FIGHTING MEASURES

- **5.1** Suitable extinguishing media Carbon dioxide, dry chemical, water spray, alcohol-resistant foam.
- 5.2 Specific hazards arising from the substance or mixture No data available

5.3 Protective equipment and precautions for fire-fighters Wear a positive-pressure self-contained breathing apparatus if necessary. Wear chemical resistant clothing as recommended by clothing manufacturer.

NFPA Rat	ing			
Health		Fire		Reactivity
hazard:	0	hazard:	0	hazard: 0

6. ACCIDENTAL RELEASE MEASURES

6.1 Personal precautions, protective equipment and emergency procedures

Apply personal protective equipment (see Section 8). Use in a properly ventilated area. Avoid breathing vapors. Avoid skin contact. Avoid eye contact. Wash hands after use. In case of large spill, remove personnel to a safe area.

6.2 Methods and material for containment and cleaning up

Apply personal protective equipment (see Section 8). Contain spill. Prevent further leakage if possible and safe to do so. Ensure proper ventilation. For small amounts, wipe or absorb spill using inert material and dispose of according to local regulations. For large amounts, evacuate area and limit access. Prevent entry of material into sewage drains and confined areas. Dispose of any contaminated materials according to local regulations.

7. HANDLING AND STORAGE

7.1 Precautions for safe handling

Do not breathe dust/fume/gas/mist/vapours/spray. Do not get in eyes, on skin, or on clothing.



SAFETY DATA SHEET (SDS)

Revision Date: 02/21/2018

Version 1.0

Part Number: 1028

7.2 Conditions for safe storage, including any incompatibilities

Refer to Section 2.2 for proper storage temperature. Store the tightly closed container in a cool, dry, well-ventilated area.

8. EXPOSURE CONTROLS/PERSONAL PROTECTION

8.1 Control Parameters

Components with limit values that require monitoring at the workplace

Component	CAS-No.	Regulatory	Value	Parameters
Boric Acid	10043-35-3	ACGIH TLV	STEL	6 mg/m ³
		ACGIH TLV	TWA	2 mg/m ³
Sodium Hydroxide	1310-73-2	ACGIH TLV	CEILING	2 mg/m ³
		OSHA PEL	TWA	2 mg/m ³
		OSHA PEL	CEILING	2 mg/m ³
				2
		NIOSH	IDLH	10 mg/m ³
		NIOSH	CEILING	2 mg/m ³

8.2 Exposure Controls

Appropriate engineering controls

Use in a properly ventilated area. Remove/wash before reuse contaminated clothing. Wash hands upon exiting work premises. Use product in an appropriately designated fume hood. Take measures to keep concentrations below acceptable limits.

8.3 Personal Protective Equipment

Eye/Face protection

Wear chemical safety goggles and/or a full face shield if splashing is possible. Keep eye wash fountain nearby.

Skin Protection

Wear chemical-resistant gloves. Gloves should be resistant to components of product. Refer to glove manufacturer for appropriate type and glove thickness.

Body Protection

No data available

Respiratory Protection No data available

Other Information None

9. PHYSICAL AND CHEMICAL PROPERTIES

9.1 Information on basic physical and chemical properties

Physical state	Liquid
Odor	No data available
Odor threshold	No data available
рН	
Melting point/freezing point	ca. 0°C (ca. 32°F)
www.newcomersupply.com	

3 of 6



SAFETY DATA SHEET (SDS)

Revision Date: 02/21/2018

Version 1.0

Part Number: 1028

Initial boiling point and boiling range Flash point Evaporation rate Flammability (solid, gas) Upper flammability or explosive limits Lower flammability or explosive limits Vapor pressure Vapor density Relative density Solubility(ies) Partition coefficient: n-octanol/water Auto-ignition temperature Decomposition temperature Viscosity ca. 100°C (ca. 32°F) No data available Similar to water No data available No data available

10. STABILITY AND REACTIVITY

10.1 Reactivity

No data available

- **10.2** Chemical stability Stable in a closed container within label-specified storage temperature and expiration date.
- **10.3 Possibility of hazardous reactions** No data available
- **10.4** Conditions to avoid No data available
- **10.5** Incompatible materials No data available
- **10.6 Hazardous decomposition products** No data available

11. TOXICOLOGICAL INFORMATION

11.1 Information on toxicological effects Inhalation exposure No data available

> Oral exposure No data available

Dermal exposure No data available

Skin corrosion/irritation No data available

Serious eye damage/irritation No data available

Respiratory or skin sensitization No data available

Germ Cell mutagenicity No data available

Reproductive toxicity Boric acid is a possible risk to an unborn child

ͶϴϢϲϘϺϴΓ

Part Number: 1028

Specific target organ toxicity - single exposure No data available

Specific target organ toxicity - repeated exposure No data available

Aspiration hazard

No data available

Acute toxicity

LD50 rat oral 2660 mg/kg LD50 rabbit dermal >2000 mg/kg LC50 rat inhalation 0.16 ppm/4H Sodium Hydroxide: LD50 rabbit dermal 1350 mg/kg

Carcinogencity

IARC: None of the components are listed NTP: None of the components are listed OSHA: None of the components are listed

Additional information

RTECS: No data available

12. ECOLOGICAL INFORMATION

- 12.1 Ecotoxicity No data available
- **12.2** Persistence and degradability No data available
- **12.3 Bioaccumulative potential** No data available
- **12.4** Mobility in soil No data available
- **12.5** Other adverse effects No data available

13. DISPOSAL CONSIDERATIONS

13.1 Waste disposal methods

Contents

Dispose of contents in a safe manner to comply with local, state and federal regulations. Contact a licensed professional waste disposal service to dispose of this material.

Contaminated packaging

Dispose of packaging in a safe manner to comply with local, state and federal regulations. Contact a licensed professional waste disposal service to dispose of this material.

14. TRANSPORT INFORMATION

14.1 DOT (US)

UN-Number
Proper shipping name
Hazard class
Packing group
Environmental hazards

No data available No data available No data available No data available No data available

SAFETY DATA SHEET (SDS)

Revision Date: 02/21/2018 Version 1.0



Part Number: 1028

15. REGULATORY INFORMATION

15.1 No data available

16. OTHER INFORMATION

Preparation Information Newcomer Supply Inc. 800-383-7799 <u>www.newcomersupply.com</u> Copyright © Newcomer Supply Inc. All rights reserved. SAFETY DATA SHEET (SDS)

Revision Date: 02/21/2018 Version 1.0